


INTERVENTO DI RECUPERO AREE BOSCHIVE
DANNEGGIATE ED ES Bosco MATERIALE LEGNOSO IN
LOCALITA' TEMELINE NEI COMUNI DI LOVERO E TOVO



Fg.15

Fg.26

Fg.16

Fg.28

 AREA DI INTERVENTO

Noga
1125.6

Cogni

VAL

Fg.26

1201.3

594

1254.4

14

1208.0

593

VALL

1230.0

Piscedo

1312.5

882

603

1408.5

Piscedo

436

881

137

36

37

38

1344.8

Fg.16

127

1505.1

Temeline

1319.0

Fg.28

1416.3

1486.3

1506.9

Alpe Gromio

1570.1

Pian del Carice

1385.6